












**ACHTUNG! ATTENTION! ATTENTION! OPGELET! OBS! OBS!**

Typ Type Type Type Type	<b>SECUMAR</b> <b>Golf 150 Twin Solas (Auto/Auto)</b>
Ersatz-Packung Spare-Kit Kit de recharge Reserveset Reservesæt Reservförpackning	<div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;"> <p><b>2x</b></p>  <p>32 g CO<sub>2</sub></p> </div> <div style="border: 1px solid black; padding: 5px;">  </div> <div style="text-align: center;"> <p><b>Art-Nr.: 927</b></p> </div> </div>
Packen Packing Emballage Invouwen Pakke instruksjon Ihoppackning	<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p><b>1.</b></p>  </div> <div style="text-align: center;"> <p><b>2.</b></p>  </div> </div> <div style="text-align: center; margin: 20px 0;"> <p><b>3.</b></p>  </div> <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p><b>4.</b></p>  </div> <div style="text-align: center;"> <p><b>5.</b></p>  </div> </div>
<b>SECUMAR SERVICE</b>	<div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;"> <p>1* Jahr/ Year/ Années/ Jaar/ Àr/ Àr</p>  </div> <div style="text-align: center;"> <p>1* Jahr/ Year/ Années/ Jaar/ Àr/ Àr</p>  </div> <div style="text-align: center;"> <p>letzter/ last/ dernier/ laatste/ sidste/ siste <b>Service</b></p>  </div> <div style="text-align: center;">  </div> </div> <p style="text-align: center; margin-top: 10px;"> <span style="font-size: 2em;">←</span> <b>10 Jahre/ Years/ Années/ Jaar/ Àr/ Àr</b> <span style="font-size: 2em;">→</span> </p> <p style="font-size: 0.8em;">                 *Empfehlung, ggf. sind andere Vorschriften zu beachten!                  *Recommendation, maybe other regulations have to be observed!                  *Recommendation, éventuellement il faut observer d'autres instructions!                  *Aanbevelen, eventueel andere/ kortere termijnen kunnen vastgesteld zijn!                  *OBS, i visse tilfælde kan andere forskrifter være gældende!                  *Observera att andra regler kan gälla lokalt!             </p>

TN 13993/01.14-SBI

Produkt-Info - Product Information - Produktinformatie - Produktinformation - Produktinformationen -



**BERNHARDT APPARATEBAU GmbH u. Co.**  
 RETTUNGSGERÄTE FÜR SCHIFFFAHRT UND LUFTFAHRT

Bredhornweg 39 Tel: +49-4103-1250  
 D-25488 Holm Fax: +49-4103-125100

## EC DECLARATION OF CONFORMITY

We hereby declare that the following specified equipment complies with the Marine Equipment Directive 96/98/EC, as amended, last amended by Directive 2008/67/EC.

### Lifejacket GOLF 150 Twin SOLAS (Auto/Auto)

Manufactured by:  
 BERNHARDT APPARATEBAU GmbH u. Co.  
 Bredhornweg 39, 25488 Holm/Germany

This equipment has been tested to verify compliance with the following Regulations and Testing Standards:

- SOLAS 74/78, amended by Reg. III/7, III/225, III/34
- IMO Res. MSC.81(70), amended by MSC.200(80) and MSC.207(81)
- IMO Res. MSC.36(63) and Res. MSC.97(73) [HSC Code]
- IMO Res. MSC.48(66) [LSA Code]

Type-Examination (Module B) Certificate No. 60363-09LUX issued by Germanischer Lloyd Luxembourg.  
 Surveillance certificate No. 60364-09LUX (Module D) issued by Germanischer Lloyd Luxembourg.

Product affixed with following mark and identification:



A Technical Construction File for this equipment is retained at the following address:  
 BERNHARDT APPARATEBAU GmbH u. Co.  
 Bredhornweg 39, 25488 Holm/Germany

Jan-Ulrich Bernhardt  
 Managing Director  
 Holm, June 16th 2010

**SECUMAR**  
**BERNHARDT APPARATEBAU GMBH U. CO.**  
 Bredhornweg 39 • 25488 Holm  
 GERMANY


ACHTUNG! ATTENTION! ATTENTION! OPELETTI! OBSI! OBSI!

TN 13993/01.14-SBI

Typ Type Type	Typ Type Type	Typ Type Type	Typ Type Type	Typ Type Type	Typ Type Type
Golf 150 Twin Solas (Auto/Auto)	SECCUMAR	Golf 150 Twin Solas (Auto/Auto)	SECCUMAR	Golf 150 Twin Solas (Auto/Auto)	SECCUMAR
Ersatz-Packung Spare-Kit Kit de rechange Reservesæt Reservesæt Reservförpackning	2x 32 g CO <sub>2</sub>	Art-Nr.: 927	1. 2. 3. 4. 5.	1* Jahr/ Year/ Années/ Jaar/ Ari/ Ar 1* Jahr/ Year/ Années/ Jaar/ Ari/ Ar	15 16 17 26
Packen Packaging Emballage Invouwen Pakke instruksjon Ihoppackning					
SECCUMAR SERVICE					

SECCUMAR  
BERNHARDT APPARATEBAU GMBH U. CO.  
Bredhornweg 39 • 25488 Holm  
GERMANY

\*Empfehlung, ggf. sind andere Vorschriften zu beachten!  
\*Recommendation, maybe other regulations have to be observed!  
\*Recommandation, éventuellement il faut observer d'autres instructions!  
\*Aanbevelen, eventueel andere/ kortere termijnen kunnen vastgesteld zijn!  
\*OBS, ! visse tilfælde kan andre forskrifter være gældende!  
\*Observera att andra regler kan gälla lokalt!



Produkt-Info - Product Information - Produktinformation - Produktinformatie - Produktinformationen

EC DECLARATION OF CONFORMITY

We hereby declare that the following specified equipment complies with the Marine Equipment Directive 96/98/EC, as amended, last amended by Directive 2008/67/EC.

Lifejacket GOLF 150 Twin SOLAS (Auto/Auto)

Manufactured by:  
BERNHARDT APPARATEBAU GmbH u. Co.  
Bredhornweg 39, 25488 Holm/Germany

This equipment has been tested to verify compliance with the following Regulations and Testing Standards:

- SOLAS 74/78, amended by Reg. III/7, III/225, III/34
- IMO Res. MSC.81(70), amended by MSC.200(80) and MSC.207(81)
- IMO Res. MSC.36(63) and Res. MSC.97(73) [HSC Code]
- IMO Res. MSC.48(66) [LSA Code]

Type-Examination (Module B) Certificate No. 60363-09LUX issued by Germanischer Lloyd Luxembourg.  
Surveillance certificate No. 60364-09LUX (Module D) issued by Germanischer Lloyd Luxembourg.

Product affixed with following mark and identification:



A Technical Construction File for this equipment is retained at the following address:

BERNHARDT APPARATEBAU GmbH u. Co.  
Bredhornweg 39, 25488 Holm/Germany

*Jan-Ulrich Bernhardt*  
Managing Director  
Jan-Ulrich Bernhardt

Holm, June 16th 2010

Bredhornweg 39  
Tel: +49-4103-1250  
Fax: +49-4103-125100

